




Identify Source of Low-level Lab Pu Contamination




Identify Source of Low-level Lab Pu Contamination



Identify Source of Low-level Lab Pu Contamination




Identify Source of Low-level Lab Pu Contamination




Identify Source of Low-level Lab Pu Contamination


Block Plot




Factor Combinations




Factor Combinations




Factor Combinations




Factor Combinations




Factor Combinations



Factor Combinations



Factor Combinations



Factor Combinations

X1: Glassware

- : Op1

+ : Op2

X2: Reagent

- : Op1

+ : Op2

X3: Sample Prep

- : CoPrec

+ : ElectroDep

X4: Tracer

- : Op1

+ : Op2

X5: Dissolution

- : Without

+ : With

X6: Hood

- : Op1

+ : Op2

X7: Chemistry

- : Without


+ : With

X8: Ashing


- : Without

+ : With


Identify Source of Low-level Lab Pu Contamination




Identify Source of Low-level Lab Pu Contamination



Identify Source of Low-level Lab Pu Contamination



Identify Source of Low-level Lab Pu Contamination



Identify Source of Low-level Lab Pu Contamination

